

Remonumentation of Certain Original Corner Points,  
T. 3 S., R. 10 W., Willamette Meridian, Oregon

CHAINS

A hemlock, 20 ins. diam., bears S. 49° W., 32 lks. dist., with scribe marks  $\frac{1}{4}$  S10 BT visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 3 S R 10 W

$\frac{1}{4}$   $\frac{S 3}{S 10}$

1978

No suitable trees available within limits.

Set a 5 ft. steel fence post alongside iron post.

The  $\frac{1}{4}$  sec. cor. of secs. 32 and 33, perpetuated and recorded by Leonard Whitmore, Deputy County Surveyor, in 1968, determined from the remains of the original bearing trees:

A sawed hemlock stump, 16 ins. diam., bears N. 22° E., 62 lks. dist., with scribe mark 4 visible on partially open blaze.

A decayed hemlock snag, size indeterminate, bears S. 40° W., 34 lks. dist., no marks visible.  
(Record, S. 35° W.)

and bearing trees mkd. by Whitmore

A spruce, 38 ins. diam., bears N. 79½° E., 49 lks. dist., with healed blaze.

A spruce, 42 ins. diam., bears S. 79° W., 31½ lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 3 S R 10 W

$\frac{1}{4}$   
S 32 | S 33

1978

Set a 5 ft. steel fence post alongside iron post.