Remonumentation of Certain Original Corner Points, T. 3 S., R. 10 W., Willamette Meridian, Oregon

CHAINS

- A spruce, 14 ins. diam., bears S. 34° W., 39 1ks. dist., with healed blaze.
- A fir, 14 ins. diam., bears N. 40° W., $15\frac{1}{2}$ 1ks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 3 S R 10 W S 9 S 10 S 16 S 15

Reset iron pipe and set a 5 ft. steel fence post alongside iron post.

The 4 sec. cor. of secs. 9 and 10, perpetuated and recorded by Leonard Whitmore, Deputy County Surveyor, in 1968, monumented with an iron pipe, 1 in. diam., firmly set, projecting 10 ins. above ground, from which the remains of the original bearing trees:

A decayed hemlock snag, size indeterminate, bears N. 85° E., 16 lks. dist., with scribe marks \(\frac{1}{2} \) S BT visible on opened blaze.

and bearing trees mkd. by Whitmore

- A hemlock, 8 ins. diam., bears S. 44° E., 21½ lks. dist., with healed blaze.
- A hemlock, 16 ins. diam., bears N. 31° W., 16 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 3 S R 10 W

14

S 9 | S 10

1978

Reset iron pipe and set a 5 ft. steel fence post alongside iron post.

The 4 sec. cor. of secs. 3 and 10, perpetuated and recorded by Leonard Whitmore, Deputy County Surveyor, in 1976, determined at record bearing and distance from the remains of the original bearing trees:

A decayed fir stump, size indeterminate, bears S. 84° E., 30 lks. dist., with fragmentary scribe marks visible on open blaze.

and bearing trees mkd. by Whitmore

A sawed fir stump, 36 ins. diam., bears N. 10½° E., 29½ 1ks. dist., with scribe marks ½ S3 BT visible on open blaze.

BOOK 6

98