

County Surveyor's Record, Tillamook County, Oregon

CHAINS

7/8/80

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 36" Hemlock bears N5°E 48 lks.; now a badly rotted hemlock stump.
- 40" Hemlock bears S59°E 24 lks.; now a badly rotted hemlock stump with burnt out face and axe work on pieces of wood.
- 8" Hemlock bears S66°W 14 lks.; now a hemlock root crown with badly rotted tree trunk laying on ground.
- 40" Hemlock bears N48°W 125 lks.; now a badly rotted hemlock stump with axe marks visible on piece of wood.

RESTORED

Var. 21 1/2°E

Set 1 1/2"x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W S11 S12 S13 S14 1980 RS1662", 35 inches in ground from which a:

- 11" Noble Fir bears S55 1/2°W 17.1 ft. to face; scribed T3NR6WS14BTRS1662.
- 23" Fir bears S12 3/4°E 20.1 ft. to face; scribed T3NR6WS13BT.
- 23" Fir bears N36°E 44.1 ft. to face; scribed T3NR6WS12BT.
- 10" Hemlock bears N49°W 9.9 ft. to face; scribed T3NR6WS11BT.

Set 4"x4"x60" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Department of Forestry metal location poster on 23" Fir BT S12 3/4°E.

Dated June 3, 1980

Restored by *Steve Ellis* under my direction.
Steve Ellis, Compassman

Present and witnessed by Othel Hendrick

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Loren R. Steele
OREGON
JULY 14, 1978
LOREN R. STEELE
1662