

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 11 and 12, T3N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 16"x10"x8", missing from which a:

30" Hemlock bears N36°E 19 lks., missing.

15" Hemlock bears N27°W 49 lks., now 18" badly decayed stub, 4 ft. high, with scribes /4S visible.

RESTORED

Var. 20½°E

Set 1½"x36" aluminium pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R8W ¼ S11 S12 1980 RS707", 32 inches in ground, in mound of rock, and from which a:

10" Fir bears S70°E 10.1 ft. to face; scribed ¼ S12 BT.

14" Fir bears N26°W 40.9 ft. to face; scribed ¼ S11 BT RS707.

Set 4"x4"x60" white painted Cedar post N64°W 3.0 ft. from corner pipe. Oregon State Forestry Department metal location poster on 10" Fir BT.

Dated December 1, 1980

Restored by Anthony Klosterman under my direction.
Anthony Klosterman, District Engineer

Present and witnessed by David B. Buchholz
David W. Wells

