

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 20, 21, 28, and 29, T3N, R9W, W.M., Tillamook County Oregon.

ORIGINAL

Post (found portion of squared fir limb, out of place, no scribes visible) from which a:

10" Hemlock bears N58°W 20 lks.; now 16" badly rotted stub, 6 feet high, scribes T3NR9S28 visible.

15" Hemlock bears S25°E 8 lks.; now 21" badly rotted stub, 7 feet high, face rotted out.

8" Hemlock bears S45°W 34 lks.; now 9" badly rotted uproot, portion of scribe visible.

7" Hemlock bears N2°E 16 lks.; now 8" stub, 4 feet high, bears N16°E 20 lks., scribe 3 visible, rest unexposed.

RESTORED

22" Hemlock corner tree, center of tree bears S73°E 1.4 feet from corner point, scribed T3NS21 on NE face, R9WS28 on SE face, S29 on SW face, and S20 on NW face, from which a:

18" Hemlock bears N55°E 26.4 feet to face; scribed T3NR9WS21BTRS 1662.

18" Spruce bears S44°W 9.6 feet to face; scribed T3NR9WS29BT.

12" Hemlock bears S09°E 10.7 feet to face; scribed T3NR9WS28BT.



12" Hemlock bears N54°W 40.6 feet to face; scribed T3NR9WS20BT.

Oregon State Forestry Department metal location poster on 18" Spruce BT.

Dated September 8, 1981.

Restored by David Buchholz under my direction

David Buchholz, Transitman



Present and witnessed by Danny Benson.