

PARKS

W 1/16 CORNER BETWEEN 5 AND 8

ESTABLISHMENT: (1979 Survey)

5/8"x30" iron rod with aluminum cap marked "OSHD STATE PARKS DIVISION."  
A galvanized steel post with paddle marked "OREGON STATE PARK BOUNDARY  
DO NOT DISTURB" 3.5' NW of rod.

15" hemlock N40°W, 25.1' to center, scribed "W 1/16 S5BT RS691" and  
attached Parks corner tag.

No trees available in Section 8.

WITNESSED BY:

R. Hemmer  
L. Boge  
R. DePuy

1/4 CORNER BETWEEN 5 AND 8

ORIGINAL:

Set a post 3' long, 3" square, 24" in the ground for 1/4 section corner marked  
"1/4S" on north face from which a:

20" hemlock bears N66°W, 24 links, marked "1/4SBT."  
7" hemlock bears S73°W, 18 1/2 links, marked "1/4SBT" (now 25" hemlock).

STATE PARKS CREW FOUND: (1979 Survey)

Brass capped iron pipe in small mound of stone marked "ORE. STATE BOARD OF  
FORESTRY" and "1/4S5 1966."  
S8

A white 4"x4" post 1.0' NW of brass cap.

20" hemlock N32 1/2°E, 11.3' to center, marked "1/2S5BT RS707" has a corner tag  
marked "1/4 COR - 10.2' S37°W."

12" hemlock stump S18 1/2°E, 18.8' to center, marked "1/2S8BT."

25" hemlock stump S79°W, 12.1' to center, with chopping to center but no  
trace of scribes at chopping, but found a trace of scribe on a root  
"BT" visible but looks like recent work.

Found downed hemlock N62°W of corner with corner tag attached, stating  
corner is 3.2' S17°E RS707.

STATE PARKS CREW SET:

Galvanized steel post with paddle marked "OREGON STATE PARK BOUNDARY DO NOT  
DISTURB" 2.0' NW of brass cap.

WITNESSED BY:

R. Hemmer  
L. Boge  
C. Middleton

SECTION CORNER 4, 5, 8 AND 9

ORIGINAL:

A 22" hemlock, now a 30" stump, which I marked: "T3N S4" on NE, "R10W S9" on SE,  
"S8" on SW and "S5" on NW, faces with 4 notches on east and 5 on south edges,  
from which a: