

# County Surveyor's Record, Tillamook County, Oregon

## CHAINS

Restored corner for Oregon State Department of Forestry in Township 3 North, Range 9 West of the Willamette Meridian in Tillamook County, Oregon. Section corner common to Sections 29, 30, 31 and 32.

Magnetic variation 21 1/2° East.

ORIGINAL- Caudle, 1882: Post; Missing.

10" Hemlock S50°W 29 lks.; Missing.

16" Hemlock N40°W 18 lks.; Now 28" stub, scribes "T3NS" exposed.

22" Hemlock N50°E 21 lks.; Now 27" rotted and badly split windfall, no marks visible.

30" Hemlock S30°E 72 lks.; Missing.

RESTORATION- Markham, 1955: 3/4" iron pipe; Found in place.

8" Hemlock N49°W 15.7 ft.; Now 23", bark scribes "T3BT1842" visible.

14" Hemlock S64°W 41.0 ft.; Now 26", axe work visible, possible face not opened.

RESTORED: Set 1 1/2"X36" galvanized iron pipe with 3" bronze cap marked "T3NR9WS30S29S31S321982RS1098", 34" in ground, over 3/4" iron pipe. From which a;

18" Hemlock bears N48°W 14.2 ft. to face scribed "T3NR9WS30BT".

24" Hemlock bears S42°E 13.3 ft. to face scribed "T3NR9WS32BT".

23" Hemlock bears N72°E 30.5 ft. to face scribed "T3NR9WS29BT".

26" Hemlock bears S64°W 39.4 ft. to face scribed "T3NR9WS31BT".

White painted cedar post 0.8 ft. SW of corner.

Yellow metal location poster on N72°E BT.

3/4" brass disks marked "RS 1098", nailed in face of new BTs.

DATED: July 16, 1982.

RESTORED BY: C. Wayne Cook, LS #1098.

PRESENT AND WITNESSED BY: D. Buchholz and D. Benson.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*C. Wayne Cook*

OREGON  
JULY 22, 1977  
C. WAYNE COOK  
1098