

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections  
8, 9, 16 and 17, T1N, R5W, W.M.,  
Washington and Tillamook Counties, Oregon.

ORIGINAL

Post (missing) from which a:

- 15" Hemlock bears N24°W 46 lks.; now a 24" stump with scribe B visible.
- 4" Vine Maple bears N42°E 86 lks.; missing.
- 4" Vine Maple bears S8°E 21 lks.; missing.
- 4" Vine Maple bears S68°W 40 lks.; missing.
- 2 Link Stream bears North 49.5'; crs. East; in place.

RESTORED

VAR 21 1/2°E

Set 2" x 36" aluminum pipe with 3 3/4" aluminum cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T1N R5W S8S9S16S17 1984 RS 1662", 26 inches in ground, with magnet insert, and from which a:

- 18" Fir bears S1°W 10.2 ft. to face; scribed T1N R5W S17 BT.
- 15" Fir bears S17 3/4°E 20.9 ft. to face; scribed T1N R5W S16 BT.
- 11" Fir bears N51 3/4°E 18.8 ft. to face; scribed T1N R5W S9 BT..
- 16" Fir bears N18 1/2°W 14.9 ft. to face; scribed T1N R5W S8 BT.

Set 4"x4"x60" white painted Cedar post S.W. 1.0 ft. from corner pipe. Oregon State Forestry Department metal location poster on 18" Fir BT.



DISTANCES MEASURED TO BT FACE  
SCALE: 1" = 10.0'

DATED: September 17, 1984

RESTORED BY:

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Loren R. Steele*

OREGON  
JULY 14, 1978  
LOREN R. STEELE  
1662

PRESENT AND WITNESSED BY: S. Ellis  
O. Hendrick

