

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 1, 6, 7 and 12, T2N, R7 & 8W, W.M., Tillamook County, Oregon.

ORIGINAL By Henry Meldrum, August 14, 1891.

36" Fir; now a 36" rotted stump with 2 notches on south side.

7" Hemlock bears N42°E 36 lks.; now missing.

6" Hemlock bears S05°E 46 lks.; now a 7" badly rotted windfall with portions of scribes visible.

6" Hemlock bears S60°W 114 lks.; now a 12" by 4 ft. rotted windfall with no scribes visible.

5" Hemlock bears N10°W 33 lks.; now missing.

RESTORATION by Louis W. Amort, RE 2311, August 15, 1952 (Book 2, page 172, Tillamook County Records).

From above corner tree a:

1 1/2" X 36" galvanized iron pipe with 3" bronze cap, in mound of stone bears East 4.0 ft.; now in place.

40" Fir stump bears S61°E 6.8 ft.; now a 40" rotted stump with scribes T2N R7W S7 BT RE 2311 visible.

54" Fir stump bears N17 1/2°E 58.9 ft.; now a 54" badly rotted stump with scribes T2N R7W S1 BT visible.

50" Fir stump bears N06°E 78.8 ft.; now a 50" stump with scribes T2N R7W S6 BT visible.

RESTORED:

Var 21 1/2° E

Set 5/8" X 36" steel rebar with yellow plastic cap marked "LS 1998", 35" inches in stump, .50 ft. East of center, and from which a:

18" Noble Fir bears S31 1/2°E 9.6 ft. to face; scribed T2NR7WS7BT.

14" Noble Fir bears S18°W 7.7 ft. to face; scribed T2NR8WS12BT.


15" Noble Fir bears N42°W 26.2 ft. to face; scribed T2NR8WS1BT.

13" Hemlock bears N56°E 27.7 ft. to face; scribed T2NR7WS6BT.


Metal location poster on 14" Noble Fir.

Dated April 6, 1987.

Restored by David B. Buchholz under my direction.
David B. Buchholz, Survey Crew Chief



Anthony J. Klosterman



Present and witnessed by Clifford R. Foster