

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner common to Sections 3 and 4, T2N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, July 29, 1893.

Basalt stone 14"x12"x10"; found downhill out of place, marks 1/4 visible.

16" Fir bears S50°W 18 lks; now a 21" stump, axe work visible on burnt out face.

14" Hemlock bears S48°E 6 lks; now badly rotted root crown, no scribes visible.

RESTORATION by Louis W. Amort RE 2311, August 15, 1952, (Book 2, Page 204, Tillamook Co. Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, in mound of stone; found out of place, from which a:

40" Fir snag bears S22 1/2°E 20.9 ft.; now a 40" stump, scribes S3 BT visible.

32" Fir snag bears N17°W 13.3 ft.; now a 32" stump, scribes 1/4 S4 BT RE2311 visible.

RESTORED

Var. 21 1/2°E

Reset pipe in correct position, 28" in ground, added marks "LS1998 1987", placed original stone on East side of pipe, in mound of rock, and from which a:


12" Noble Fir bears S25°W 21.9 ft. to face; scribed 1/4S4BT.

8" Fir bears S34°E 10.8 ft. to face; scribed 1/4S3BT.

4"x4"x60" white painted Cedar post N61°E 2.2 ft. of corner pipe. Metal location poster on new BTs. Also poster on 24" Fir stump N75 1/2°E 5.9 ft.

Dated April 29, 1987.

Restored by



Present and witnessed by David B. Buchholz
Clifford R. Foster