

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner common to Sections 12 and 7, T2N, R7&8W, W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, August 14, 1891.

16" x 10" x 8" stone with 1/4 on West face; found buried 1.5 ft. NE of pipe with 1/4 on North face.

28" Fir bears East 67 lks.; missing.

16" Hemlock bears N17°W 50 lks.; missing.

RESTORATION by Louis W. Amort RE2311 August 15, 1952, (Book 2, Page 175, Tillamook Co. Records).

1 1/2" Galvanized iron pipe with 3" bronze cap; found out of place.

54" Fir snag bears S74°E 82.2 ft.; now a 54" rotted stump with portions of scribes visible.

52" Noble Fir bears N47°W 59.0 ft.; now a 29" by 6 ft. high badly broken and rotted stub, no scribes visible.

RESTORED Var. 21 1/2°E  
Reset above pipe, 36" in ground with marks "T2N R8W R7W 1987 LS1998" added. Placed original stone on North side of pipe, and from which a:

18" Grand Fir bears N44°W 26.6 ft. to face; scribed 1/4S12BT.

21" Grand Fir bears N15°E 27.4 ft. to face; scribed 1/4S7BT.


Metal location poster on new BTs.

Dated May 7, 1987.

Restored by David B. Buchholz under my direction.  
David B. Buchholz, Survey Crew Chief



*Anthony J. Klosterman*



Present and witnessed by Clifford R. Foster

BOOK 6