

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 33, 34, 3 and 4, T2 & 3S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL By Albert P. Wilson, June 17, 1891.

Post; missing, point falls in cat road.

- 30" Hemlock bears N37°W 23 lks.; missing.
- 48" Fir bears N28°E 61 lks.; now a 56" stump with portions of scribes S34 visible.
- 12" Fir bears S50 1/2°E 15 lks.; missing.
- 50" Fir bears S60°W 8 lks.; now a 63" stump on west edge of cat road and covered with dirt.

RESTORATION by Louis W. Amort, RE2311, August 15, 1952 (Book 2, page 160, Tillamook County Records).

Corner point falls in cat road:

- 1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground, in mound of rock, set as reference monument bears East 23.0 ft.; found pipe bent over, mound of rock missing. Distance 21.6 ft.
- 42" Fir stub bears S09 1/2°E 101.0 ft. from corner point; now a 42" rotted stub with scribes T3S R7W S3 BT visible.
- 20" Fir snag bears N17 1/2°E 35.3 ft. from corner point; now a 20" snag with scribes T2S R7W S33 BT RE2311 visible.
- 14" Fir stub bears S84°W 10.4 ft. from corner point; now a 14" rotted stub with scribes T3S R7W S4 BT visible.

RESTORED

Var 21 1/2°E

At true corner point I set a 1 1/2"x30" Aluminum pipe with 3 3/4" cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T2S R7W S33 S34 S4 S3 T3S 1987 LS1998", 28 inches in ground, from which a:

- 18" Fir bears N19°E 27.5 ft. to face; scribed T2SR7WS34BT.
- 7" Fir bears N67°W 17.9 ft. to face; scribed T2SR7WS33BT.
- 25" Fir bears S21°E 42.5 ft. to face; scribed on root T3SR7WS3BT.
- 4" Fir bears S11°W 49.3 ft. to face; scribed X BT.

4"x4"x60" white painted Cedar post S83°E 8.6 ft. from corner pipe.  
Metal location poster on new BTs.


Also brass washers marked "LS1998" on new BTs.

Also poster on 14" Fir BT S84°W 10.4 ft.


Dated July 8, 1987.

Present and witnessed by David B. Buchholz  
Clifford R. Foster

Restored by



*Anthony J. Klosterman*



BOOK 6