

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner common to Sections 4 and 5, T3N, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL By Henry Meldrum, September 13, 1893.

15"x8"x6" stone; missing.

20" Fir bears N78°E 53 lks.; missing.

30" Fir bears S83°W 56 lks.; now a 36" badly rotted
stump with axe work visible on burnt out face.

8 lk. Creek course West bears South 250 lks.; in place, course
N70°W.

RESTORED August 28, 1987

Var 21 1/2°E

Set 1 1/2"x30" Aluminum pipe with 3 3/4" cap marked "STATE OF
OREGON DEPARTMENT OF FORESTRY T3N R7W 1/4 S5 S4 1987 LS1998",
28" in ground, and from which a:

21" Fir bears N42°E 10.0 ft. to face; scribed 1/4S4BT.

8" Fir bears N39°W 40.9 ft. to face; scribed 1/4S5BT.


Metal location poster on new BTs.

Also brass washers marked "LS1998" on new BTs.


4"x4"x60" white painted Cedar post bears S79°W 3.1 ft. from pipe.

Present and witnessed by David B. Buchholz and Clifford R. Foster.

Restored by



Anthony J. Klosterman



BOOK 61

- 336 -