

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 1, 6, 31 and 36, T1&2S, R6&7W, W.M., Tillamook and Washington Counties, Oregon.

ORIGINAL by Caudle & Brand, November 4, 1879.

Point falls in 10 lk. brook course SW, no monument set; point falls in dry creek bed course S15E from N36W.

48" diameter x 36" high stone mound bears East 8 lks. on East bank of brook; found a 48"x18" high mound in place.

REWITNESSED by Albert P. Wilson, May 18, 1891.

From the true corner point a:

- 4" Vine Maple bears N10 1/2E 43 lks.; missing, Vine Maple clump at this location.
- 8" Hemlock bears S73 1/2E 43 lks.; now a 10"x7 ft. long badly rotted windfall with no face visible.
- 48" Hemlock bears N73 1/2W 82 lks.; now a 48"x35 ft. long badly rotted windfall with no face visible.
- 48" Hemlock bears S73 1/2W 39 lks.; now a 50"x4 ft. high broken stub with portion of scribe and chaining notch visible on burnt face. Distance measured on the slope.

RESTORATION by L.H.L. Lumber Corporation, 1949 (unrecorded).

3/4" iron pipe with 2 1/2" bronze cap set at true corner point; in place 8" above ground.

RESTORATION by Louis W. Amort RE2311, August 15, 1952 (Book 2, page 183, Tillamook County Records).

Raised mound of stone around pipe; in place.

- 66" Fir stump bears N61E 65.6 ft.; now 6 ft. high with portions of scribes T1S R S31 BT visible.
- 36" Fir stump bears S30E 78.3 ft.; now 2 1/2 ft. high badly rotted with portions of scribes T2S R6W S6 B visible.
- 42" Fir stump bears S05W 53.2 ft.; now 3 ft. high badly rotted with scribes T2S R7W S1 BT RE2311 visible.
- 30" Fir stub bears N54W 30.9 ft.; now 7 ft. high badly rotted with portions of scribes T1 R7 S36 BT visible.

CONTINUED ON NEXT PAGE

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Anthony J. Klosterman

OREGON
JULY 16, 1982
ANTHONY J. KLOSTERMAN
1988

4907 Third St.,
Tillamook, Oregon 97141

Page 1

