

TILLAMOOK COUNTY SURVEYORS OFFICE

Meander corner common to sections 31 & 32 T.4S.,R.10W.,W.M.

T4SR10W
S31|S32

RS 287
1972

I set a 10" cast iron Tillamook County monument case around a found 2" iron pipe with 3" Tillamook County brass cap; (see Tillamook County Surveyors rewitness card #795).

History of found Monument

I found this monument to be as reported on Tillamook County Surveyors rewitness card #795 and the accessories found and/or set at that time to now be as follows:

24" Spruce S.17*W. 60.40'; (Now 30" rotten stump 7' high scribing visible).*

24" Spruce South 97.45'; (Now 28" rotten stump 8' high scribing visible).*

84" hat section post N.72*E. 10.0'; (This post had been flattened by road maintenance crews, I reset at N.72*E. 10.6').*

* Indicates yellow Tillamook County corner tag affixed.

Surveys and rewitnesses of reference;

G.L.O. 4S10 page 41 1879 . (no original evidence found)
B-651 John L. Carlich L.S. 287 1973 .
Field notebook P5 page 7, William E. Anderson 1927 .
Survey book S3 pages 80 & 81 Andrew M. Austin 1896(ama 12 page 4)
B-838 C. Wayne Cook L.S. 1098 1979 .

New Accessories

Power pole #060000 S.8*W. 61.30'; The distance was measured to a nail with brass Tillamook County washer in a scribed triangle on the side of the pole.

*indicates yellow metal Tillamook county corner tag affixed.

Monument Location

This corner is located approximately in the center of the North bound lane, towards Pacific City, of Brooten County Road.

In the presence of Dan McNutt & Al Dvorak

June 1989

Title Allen E. Duncan, C.S.

