

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner common to Sections 1 and 36, T1&2N, R10W, W.M.,  
Tillamook County, Oregon.

ORIGINAL by C.J. Handley, July 1, 1873.  
Post, in mound; missing.

6" Vine Maple bears S20W 16 lks.; missing.  
5" Hemlock bears N3E 6 lks.; missing.

RESTORATION by A.M. Austin, County Surveyor, August 21, 1897,  
Book S3, page 134, also Book AMA 14, page 66 Tillamook  
County Records.  
Cedar stake; missing.

REESTABLISHMENT by John L. Carlich, Deputy County Surveyor, LS287,  
Summer, 1958. Plat #B-389 Tillamook County Records.

1 1/2" Galvanized Iron pipe with 3" bronze cap marked S36 S1 1/4;  
found in place, flush with ground.

24" Hemlock bears N9 3/4W 67.67 ft.; now a 24" rotted stump  
with no scribes visible.  
40" Hemlock bears S43 1/2W 50.07 ft.; now a 40" uprooted stump  
with no scribes visible.  
4"x2"x48" post SE 2.5 ft.; now down and rotted.

REWITNESSED October 31, 1989


Var. 21 1/2 E

From above pipe with marks "LS1998 1989" added and from which a:


13" Fir bears N25E 28.7 ft. to face; scribed 1/4S36BT.  
12" Spruce bears N89 1/2W 28.6 ft. to face; scribed 1/4S36BT.  
8" Hemlock bears S32 1/2E 13.6 ft. to face; scribed 1/4S1BT.  
12" Creek bears West 13 ft.; course S20E by N20W.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.  
Present and witnessed by David B. Buchholz and Clifford R. Foster.



*Anthony J. Klosterman*



4907 Third St.,  
Tillamook, Oregon 97141