


TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 Corner Common to sections 9 & 10 T.1N.,R.10W.,W.M



I set a 10" concrete cylinder around found O.S.B.F. 1 1/2" iron pipe with 3" bronze cap set in 1961, (See Tillamook County Surveyors map #B-437).

History of found monument

This is a proportion corner set by O.S.B.F.

I found this monument to be as described on the above said map and the bearing trees set at that time to now be as follows:

*58" cedar N.22*W. 3.9'; (Now 60" cedar stump, scribing visible on partially healed, burnt face).

*72" cedar S.71 1/2*E. 22.9'; (Now 72" cedar stump, scribing visible on partially burnt, open face).

*84" hat section post S.68*W. 2.9'.

*indicates Tillamook County Surveyors yellow metal location poster attached.

Monument location

This corner is located approximately 75' East of a landing on a very steep slope.

In the presence of Dan McNutt and Al Dvorak

March 1990

Title

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan Duncan, C.S.

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
793

