

TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 Corner Common to Section 13 T.4S.,R.8W.,W.M.
 and
 Section 18 T.4S.,R.7W.,W.M.

T4S
 R8W 1/4 R7W
 |
 S13 . S18
 |
 1980
 PLS 1826

I found a 2 1/2" iron pipe with 3" U.S.D.A. aluminum cap which I encased in a 10" concrete cylinder. (See Tillamook County Surveyors map #B-960).

History of found monument

I found this monument and its' accessories to be as reported on Tillamook County Surveyors map B-960.

Surveys and rewitnesses of reference:

B-960	1980	David L. Lorence LS 1826 & Kenneth M. Wightman II LS 942
-------	------	--

(Also see Tillamook County microfilm file notes of U.S.G.L.O. and B.L.M. surveys).

Monument location

This corner is located approximately 50' Northwest of a gravel logging road at the west edge of a recent clear-cut.

In the presence of Dan McNutt and Al Dvorak

March 1990	Title
------------	-------

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
JULY 14, 1967
 ALLAN E. DUNCAN
 793

3/29/90

TILLAMOOK COUNTY

 MAR 30 1990

 SURVEYORS OFFICE