

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 1, 2, 35 and 36, T1 and 2N, R10W,
W.M., Tillamook County, Oregon.

ORIGINAL by C.J. Handley, July 1, 1873.

Post in mound; missing.

10" Spruce bears N08E 18 lks.; missing.

4" Hemlock bears S48E 22 lks.; missing.

RESTORATION by A.M. Austin, C.S. August 21, 1897, book AMA 14, page 66,
Tillamook County Records.

4" Hemlock post; missing.

RESTORATION by O.R. Miller of Longview Fibre Co., June 21, 1951
(Book 3, page 1 and 12, Tillamook County Records).

Iron Pipe; found 1" stainless steel pipe 4" above ground, in place.

14" Hemlock bears N67W 29.7 ft.; missing.

24" Hemlock bears S84W 31.8 ft.; now a 21" x 15 ft. high badly
rotted snag with portions of scribes S2 visible on open
face.

14" Hemlock bears S54E 16.1 ft.; now a 19" x 12 ft. high rotted
stub with portions of scribes visible on open face.

16" Spruce bears N60E 35.5 ft.; now a 20" x 4 ft. high badly
rotted stump with edge of face visible.

RESTORED December 18, 1990

Var. 21 1/2 E

Placed a 1 1/2" x 30" Aluminum pipe with 3 3/4" cap marked "STATE OF
OREGON DEPARTMENT OF FORESTRY T2N R10W S35 S36 S2 S1 T1N 1990

LS1998", 28" in ground, over Miller's pipe, and from which a:

18" Hemlock bears N72 1/2E 56.0 ft. to face; scribed T2NR10W
S36BT.

14" Hemlock bears S17 1/2E 47.3 ft. to face; scribed T1NR10W
S1BT.

9" Hemlock bears S43 1/2W 41.2 ft. to face; scribed T1NR10W
S2BT.

11" Alder bears N13W 10.05 ft. to barkscribes T2NR10WS35BT.

NOTE: Corner falls under powerlines.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Clifford R. Foster.

Restored David B. Buchholz under my direction.

David B. Buchholz, LS2272

