

TILLAMOOK COUNTY SURVEYORS OFFICE
COURTHOUSE, TILLAMOOK, OREGON 97141

SMC CORNER EAST-WEST CENTERLINE SECTION 24 T.4S., R.11W., W.M.

SMC | S I found a 1 1/2" iron pipe with a 3" Tillamook County
C +----C Surveyors Brass Cap 5' deep in the sand (see T.C.S.
| 24 Rewitness #811). I set a 2"X 36" iron pipe with 3"
RS 793 Tillamook County Surveyors Brass Cap approximately
1991 1 foot deep and encased in concrete above the found
monument.

History of found monument

I found this monument to be as described in said T.C.S. Rewitness and the references found and/or set at that time to now be as follows:

Surface monument set in 1983 ; (Gone, destroyed by sand removal) .

Easterly bolt in the NE cor foundation of dwelling S.21°W. 12.29';
(Found O.K.) .

60" hat section post 1.5' West; (Gone, destroyed by sand removal) .

84" hat section post 1.0' East; (Gone, destroyed by sand removal) .

*indicates Tillamook County Surveyors yellow metal location poster attached.

New Accessories

2"X 4"X 96" treated post 0.9' East.

Surveys and Rewitnesses of record not listed on rewitness #811

A-4880	4-25-83	Allan E. Duncan LS 793
C-340	9-30-71	Lester E. Fultz PE 4571
Rewitness bin #811	4-1983 & 12-88	Allan E. Duncan LS 793 C.S.

Location of Monument

This corner is located in loose sand at the toe of a sand dune on the North side of a dwelling.

In the presence of Al Dvorak and Dan McNutt

June 25, 1991

Title:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
793

