

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 4, 5, 8 and 9, T1S, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, November 1, 1891.
Post; missing.

- 4" Hemlock bears N31W 39 lks.; now a badly rotted uproot
with portions of scribes visible.
- 7" Hemlock bears S76W 18 lks.; missing.
- 18" Hemlock bears S51E 36 lks.; missing.
- 18" Hemlock bears N21 1/2E 207 lks.; now a 24" x 3 ft. high
badly rotted stub with no scribes visible.
- 8 lk. Creek course West turns NW bears N00 03W 0.85 chains;
in place.

RESTORATION by Louis W. Amort RE2311, February 25, 1954 (Book 1,
page 187, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 34" in
ground in small mound of stone; in place.

- 4" Fir bears N47W 28.0 ft.; now 24" with face closed.
- 72" Fir stump bears S23 1/2W 78.4 ft.; now badly rotted with
scribes T1S R7W S8 BT RE2311 visible.
- 59" Fir stump bears S42E 38.2 ft.; now rotted with scribes
T1S R7W S9 BT visible.
- 60" Cedar snag bears N27E 170.0 ft.; now a 60" x 7 ft. high
burnt stump with scribes T1S R7W S4 visible.
- 5"x5"x60" white painted Cedar post 1.0 ft. SW of pipe; in
place.

REWITNESSED June 3, 1992

Var. 19 1/2E

From above pipe with marks "LS1998 1992" added a:

- 17" Fir bears S42W 35.0 ft. to face; scribed T1SR7WS8BT.
- 24" Fir bears N47W 27.2 ft. to face (above Amorts face);
scribed T1SR7WS5BT.
- 16" Fir bears S50E 48.8 ft. to face; scribed T1SR7WS9BT.


Metal location poster on new BTs.

Also 1954 metal location poster on 59" Fir stump BT.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by David B. Buchholz and Trina Contreras.

Rewitnessed by



Anthony J. Klosterman
OREGON
JULY 16, 1982
ANTHONY J. KLOSTERMAN
1998

