

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY  
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 4 and 5, T1S, R7W, W.M.,  
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, November 9, 1891.  
Post; missing.

30" Hemlock bears S58E 27 lks.; now a 30" badly rotted stump  
with no scribes visible.

30" Hemlock bears S45 1/2W 27 lks.; now a 34" x 10 ft. high  
badly rotted stub with portions of scribes 1/4 S  
visible.

Note: Distance measured from center of BTs.

RESTORATION by Louis W. Amort RE2311, November 12, 1953 (Book 2,  
page 314, Tillamook Co. Records.)

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in  
ground, in mound of stone; now 34" in ground, in place.

56" Fir stump bears S36E 35.6 ft.; now badly rotted with  
scribes 1/4 S4 BT RE2311 visible.

84" Fir stump bears S14W 63.6 ft.; now badly rotted with  
no scribes visible on rotted out face.

REWITNESSED June 3, 1992

Var. 19 1/2 E

From above pipe with marks "LS1998 1992" added, a:

24" Fir bears N88E 29.4 ft. to face; scribed 1/4S4BT.

18" Fir bears N66W 38.8 ft. to face; scribed 1/4S5BT.

Metal location poster on new BTs.

Also 1953 tag on 56" Fir stump BT.

3"x4" white painted Cedar post 1.2 ft. NW of corner pipe.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by David B. Buchholz and Trina Contreras.

Rewitnessed by

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Anthony J. Klosterman*  
OREGON  
JULY 16, 1982  
ANTHONY J. KLOSTERMAN  
1998

