

TILLAMOOK COUNTY SURVEYORS OFFICE
201 LAUREL AVENUE
TILLAMOOK, OREGON 97141

1/4 CORNER SECTION 14 & 23, T.1N.,R.6W.,W.M.



I Found A 1 1/2" iron pipe with a 3" O.S.B.F. Bronze Cap (Tillamook County Surveyors Rewitness Book 2 Page 106). I encased the found I.P. in a 10" concrete cylinder.

HISTORY OF FOUND MONUMENT

I found this corner to be as reported in Tillamook County Surveyors Rewitness Book 2 at Page 106 and the accessory evidence, found at that time, to now be as follows:

(G.L.O.) 10" hemlock S32°E 42 links, reported in book 2 page 106 as a 16" stub scribe marks 1/4 exposed; (Now gone).

(G.L.O.) 24" hemlock N41°E 33 links, reported in book 2 page 106 as "only roots remain"; (Now gone).

(Book 2 Page 106) 54" fir stump N55°E 12.8'; (Found, 8' high fir stump, at position, scribing visible on weathered face, faded old O.S.B.F. yellow metal location poster attached).

(Book 2 Page 106) 48" fir stump S04°W 51.8' three railroad spikes driven in top of stump, (Found, now 6' high rotten stump, at position).

New Accessories

*11" fir S24°E 6.65' scribed 1/4S23BTCS. Measurements were taken to a nail with a brass washer inscribed "T.C. SURVEY" in the face between the scribed "B" & "T".

*18" fir N43°E 4.20' scribed T1NR6W1/4S14BTCS. Measurements were taken to a nail with a brass washer inscribed "T.C. SURVEY" in the face between the scribed "B" & "T".

*72" light hat section post South 1.5'.

* indicates Tillamook County Surveyors yellow metal location poster attached.

Rewitness References of Record

Book 2 Page 106

12-31-51

Louis W. Amort PE 2311

G.L.O. Book 1N6 Page 21

09-24-1874

J.A. Hurlburt, Contract #215


Location of Monument

This corner is located ±400' East of Beaver Dam Forest Road, on a Northerly slope, ± S60°E 50' of aspring.


In the presence of Al Dvorak and Dan McNutt

December 21, 1993

Title:



Allan E. Duncan, C.S.



EXPIRES 12-31-95