

RESTORED CORNER FOR OREGON DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 3, 4, 9 and 10, T2N, R9W,
W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, July 28, 1884.
18" x 8" x 8" Basalt stone; missing.

- 4" Vine Maple bears N62W 20 lks.; missing.
- 10" Hemlock bears N41E 95 lks.; missing.
- 54" Spruce bears S39E 72 lks.; now a 8' high badly rotted
stump with portions of scribes and axe work visible.
- 6" Vine Maple bears S38W 23 lks.; missing.

NOTE: Corner set from BT face which is consistent with other
corners found in this township.

REFERENCED: A 1930's Hammond Lumber Company engineers topographic
map shows the corner to be a stone with a 54" Spruce BT and a bench
mark on a 96" Spruce with no bearing or distance. A 75" x 9' high
badly rotted Spruce stump bears S22E 27.5 ft. to an apparent face
with axe work visible.

RESTORED August 23, 1994

Var. 19 1/2E

Set a 1/2" x 30" Aluminum pipe with 3 3/4" bronze cap 27" in
ground, in mound of stone, and from which a:

- 19" Alder bears S58 1/2E 39.6 ft. to bark scribes;
T2NR9WS10BT.
- 36" Cedar bears N86W 70.6 ft. to face; scribed T2NR9WS4BT.
- 15" Alder bears N18 1/2W 1.5 ft. to bark scribes
T2NR9WS4BT.
- Centerline of Anderson Creek Grade Road bears North 29.5 ft.
course S74E by N74W.

Metal location poster on new BTs.
3/4" brass washer marked "LS2272" nailed to face of new BTs.
Present and witnessed by Clifford R. Foster.

Restored

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Buchholz

OREGON
JULY 16, 1987
DAVID B. BUCHHOLZ
2272

Expires 12/31/95

