

**TILLAMOOK COUNTY SURVEYORS OFFICE
201 LAUREL AVENUE
TILLAMOOK, OREGON 97141**

S 1/16 CORNER SECTIONS 9 & 10, T.2S.,R.9W.,W.M.



I found a 2" iron pipe, 10" deep, no plug, (See Map A-562)
I set a 5/8" X 12" iron rod with a 3" Tillamook County
Surveyors Brass Cap inside of the found 2" iron pipe and
encased in concrete approximately 6" deep.

HISTORY OF FOUND MONUMENT

I found this monument to be as described in T.C.S. Rewitness Book 5 at
Page 131 and the references found and/or set at that time to now be as
follows:

(Rewitness Book 5 Page 131) U.S.N/ 6"X6" conc. monument with copper wire West
20.00'; (Not Found).

(Rewitness Book 5 Page 131) SW corner of house N28°E. 58.25'; (found, at
position).

(Rewitness Book 5 Page 131) Power Pole #19 S25°E. 48.97'; (found, at
position).

NEW ACCESSORY

*72" LIGHT HAT SECTION POST N44°W 21.16'.

* INDICATES TILLAMOOK COUNTY SURVEYORS YELLOW METAL LOCATION POSTER ATTACHED.

SURVEYS AND REWITNESSES OF RECORD

A-562	DECEMBER 1953	WILLIAM E. ANDERSON	PE 1697
A-1479	AUGUST 1967	JOHN L. CARLICH	RS 287
A-1685	MARCH 1969	JOHN L. CARLICH	RS 287
A-4043	DECEMBER 1979	FREDERICK M. GAYLORD	LS 929
P-15	AUGUST 1990	DONALD MARX	LS 332
REWITNESS BOOK 1 PAGE 83	1949	W.E. ANDERSON	C.S.
REWITNESS BOOK 4 PAGE 63	1949	W.E. ANDERSON	C.S.
REWITNESS BOOK 5 PAGE 131	12-10-1970	JOHN L. CARLICH	RS 287


Location of Monument

This corner is located approximately 20' East of a chain link fence in
a grassy approach to a gate to an open field on the Port of Tillamook Bay
property near a point of intersection of centerline tangents on a ± 90°
delta curve in Brick Yard Road.


In the presence of Al Dvorak and Dennis Wood

June 5, 1996

Title:



Allan E. Duncan, C.S.



EXPIRES 12-31-99