

OREGON CORNER RESTORATION FORM

Township 1 North Range 7 West Sections 4 & 9

County: Tillamook Date: 7-25-1997


Corner Designation: W 1/16 Corner  $\frac{4}{9}$  X Referenced Out

Previous Renewals/Surveys, etc: Not researched.


Monument Found (Condition and Source): Found 3" brass cap on 2" o.d. galvanized iron pipe, 2" above ground surface, marked as shown below. Found a fallen white-painted cedar post, approximately 2"x6"x5 feet, with tip near NE side of the cap.  
Note: Oregon LS#199 = Lyle Beyers

Accessories Found: None.

Monument Detail



Sketch



Monument Set: None

New Accessories: Nailed a yellow aluminum Willamette Industries tag to the following:  
- 22" dbh Douglas-fir, N86E, 37.5'  
- 16" dbh Alder, N64W, 17.5'  
- Left of double 14" alder, N16W, 13.0'  
Also noted a 40" dbh old stump, 4' high, not tagged, N20E, 25'

Location & Comments: Corner falls several feet inside the NNE edge of a 50-foot diameter vine maple patch.

Hand Compass Declination: 20E  
Firm/Agency: Willamette Industries  
North Coast Timber & Logging  
PO Box 998  
Seaside, OR 97138  
Party Chief: Andy Blachly  
Notes: Andy Blachly  
Witness:

Surveyor's Seal

