

RESTORED CORNER FOR OREGON DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

Witness corner common to Sections 15, 16, 21 and 22, T3N, R8W,
W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, October 18, 1891.

16"x12"x6" Basalt stone 11" in ground with 3 notches on South
and East edges; now missing, area has been scarified for a
rock pit.

48" Hemlock bears N54°E 9 lks.; missing, point falls in
scarified area.

18" Hemlock bears S44°E 50 lks.; missing, point falls in
scarified area.

48" Hemlock bears S50°W 27 lks.; missing, point falls in
scarified area.

10" Hemlock bears N66½°W 18 lks.; missing, point falls in
scarified area.

Top of ridge bears N89°32'E 0.30 chains, slopes North; in
place.

Top of main spur bears S00°03'E 5.00 chains, course North by
S20°W; in place, point falls in saddle.

RESTORED May 17, 2001

Var. 25¼°E

From top of main ridge, set a witness corner N00°03'W 478.0 feet
from ridge call. At the corner I set a 1½"x40" galvanized iron
pipe with 3¼" bronze cap marked "STATE OF OREGON DEPARTMENT OF
FORESTRY WCT3NR8WS16S15S21S22 S0-03E148.0FT2001LS2272", 40" in
ground, from which a:

16" Fir bears N58½°E 16.55 ft. to face; scribed XBT.

14" Fir bears S47°E 143.5 ft. to face; scribed XBT.

13" Fir bears S35°W 130.4 ft. to face; scribed XBT.

12" Alder bears N40½°W 8.6 ft. to face; scribed XBT.

Metal location poster on BTs.

3/4" brass washer marked "LS2272" nailed to face of new BTs.

6 ft. orange carsonite post bears N11°E 1.15 ft.

Centerline of Sibley Road bears South 29.0 ft. course N72°E by
S86°W.

Present and witnessed by Clifford R. Foster.

Restored by



SURVEYED BY:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Buchholz

OREGON
July 16, 1987
David B. Buchholz
2272

4907 Third Street
TILLAMOOK, OR 97141
EXPIRES DECEMBER 31, 2001