

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> Section 14	<b>TOWNSHIP</b> 3 South	<b>RANGE</b> 8 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 09-05-07
<b>CORNER DESIGNATION:</b> The one-quarter corner common to Sections 13 and 14, Township 3 South, Range 8 West, W.M., Tillamook County, Oregon.		<b>(Please check one)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not found
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out
<b>Previous Rewitnesses, Restorations and Surveys, etc.:</b> Map A-859, Map A-2711, Tillamook County Survey Records. Bureau of Land Management field notes Volume: OR-R0569 Page: 0391.0.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3-1/4" diameter Bureau of Land Management brass cap and pipe in good condition. The 6" [6"] diameter dead fir described on page 391 of the BLM field notes is now gone. Found, at the record position, a 5' tall x 30" [30"] diameter fir stump with a partly rotted face bears [S. 80° E., 22 lks.] with no scribe marks visible. Found, at the record position, a 6' tall x 17" [17"] diameter fir stump with an aluminum nail in a partly rotted face bears [N. 66° W., 30 1/2 lks.] with no scribe marks visible. [ ] indicates record value from Bureau of Land Management field notes Volume: OR-R0569 Page: 0391.0.		
<b>Monument Set (Procedures and Description):</b> Not applicable.	<b>Sketch of found Monument:</b> <div style="text-align: center;"> </div>	
<b>Other new accessories set:</b> Set a 72" hat section post with yellow metal location tag South 2.6'. We also placed a 12" diameter plastic cylinder around the found monument. The plastic cylinder was filled with 60 pounds of concrete.		
<b>Unrecorded Bearing Trees:</b> Found a 14" diameter Douglas Fir tree with a healed face. We chopped into the healed face and found a nail and brass washer stamped "LS 793" which bears South 55° East 13.15'. This found accessory is an unrecorded bearing tree. Found 17" diameter Douglas Fir tree with a healed face. We chopped into the healed face and found a nail and brass washer stamped "LS 793" which bears North 22° West 5.92'. This found accessory is an unrecorded bearing tree.		
<b>Location &amp; Comments:</b> This corner is located approximately 100' North of a creek on a Southwesterly facing slope.		
<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		<b>SURVEYOR'S SEAL</b>  <div style="border: 1px solid black; padding: 5px; display: inline-block;">           REGISTERED            PROFESSIONAL            LAND SURVEYOR         </div> <i>Danny R McNutt</i> <div style="border: 1px solid black; padding: 5px; display: inline-block;">           OREGON            JULY 11, 2000            DANNY R. MCNUTT            49230         </div> RENEWAL 12-31-2007
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor		
<b>Notes:</b>		
<b>Witness:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor		

