

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 11	TOWNSHIP 3 South	RANGE 10 West
COUNTY: Tillamook		DATE: 3-25-09
CORNER DESIGNATION: The North 1/16 th Corner Common to Sections 10 and 11, T. 3 S., R. 10 W., W.M.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: Map A-1008 (1962), Map A-2429 (1973), Map B-1689 (1993), Partition Plat P-278 (1995), Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" Brass Cap flush with ground, good condition in an old downed fence line. The monument is stamped as shown hereon. Found white cedar post lying down near monument. (Map A-1008) – Found 29" diameter Fir Stump, (was 24"), 6' tall, healed scar, rusted tag, chopped-out face to reveal scribing "N1/16 S11 BT". Set a nail & washer between the "11" and "B" in the scribe, bears (East 9.9'). (Map A-1008) – Found 35" diameter Double Hemlock Broken Snag, (was 29"), 8' tall, healed scar, tag. Set nail & washer in healed scar, bears N 39° W 7.5' (N 36 1/2° W 7.7'). All set nails have an aluminum washer marked, "Till. Co. Surveyor". () Indicates Map A-1008 record information, Tillamook County Survey Records.		
Monument Set (Procedures and Description): Not applicable.	Sketch of Found Monument: <div style="text-align: center;"> </div>	
New accessories set: Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Set a hat section post with a yellow metal location poster North 3.0' from monument.		
New Bearing Trees set: 9" diameter Hemlock bears N 44° E 10.5', scribed, "N 1/16 S11 BT", tagged and painted. 32" diameter Cedar bears S 33° W 34.4' measured at slope, calculated horizontal distance is 33.2', scribed, "N 1/16 S10 BT", tagged and painted. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T, and a yellow metal location tag affixed.		
Location & Comments: Corner is located approx. 150' south of a main gravel logging road, at the base of a steep slope.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div>
Notes:		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 RENEWAL DATE: 06-30-09 </div>
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician		

