



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: Southwest ¼ of the Northwest ¼ Section 2	TOWNSHIP 1 South	RANGE 10 West
COUNTY: Tillamook		DATE: 09-01-09
The Centerline-Centerline intersection at Warren and McCoy Streets in the City of Bay City		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input checked="" type="checkbox"/> Brass Cap set at surface
<input checked="" type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc: Survey maps A-581, A-1029, A-1246, A-1211, A-2662, A-6477, A-2718, A-2815, A-6090, A-6037, A-4068, A-4689, A-5733, A-7076, B-1329, B-1979, BV-1980, B-2104, P-145, P-146, F-41-109, Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Surveyor Brass Disk in a 9" cast iron monument box, which is encased in concrete. The monument has been covered over due to an asphalt paving project. This monument is now a subsurface monument and found to be as described in Map A-5733.		
Monument Set (Procedures and Description): Set a 2" diameter brass cap in concrete at the road surface. The 3" diameter Tillamook County Brass Cap was covered over during a recent asphalt paving project. The 2" diameter cap is stamped as shown hereon.	Sketch of Monument Set at Surface:	
		
New accessories set: Set a 5/8" X 30" rebar with yellow plastic cap stamped "TILLAMOOK CO. RANDOM" on line with the centerline of Warren Street which bears North 00° 00' 44" West at a distance of 25.08'.		
New Bearing Trees set: No new bearing trees were set.		
Location & Comments:		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141	SURVEYOR'S SEAL  <i>Danny R. McNutt</i>	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes: Digital images were taken of the set surface monument and subsurface monument.		
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

