

OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 15 & 22		TOWNSHIP: 2 SOUTH		RANGE: 9 WEST	
COUNTY: TILLAMOOK, OREGON				DATE: 14-Aug-13	
CORNER DESIGNATION: NORTHEAST CORNER OF SECTION 22, SOUTHEAST CORNER OF SECTION 15				(Please Check One)	
				<input type="checkbox"/> Condition Report Only	
				<input type="checkbox"/> Restoration	
				<input checked="" type="checkbox"/> Rewitness	
				<input type="checkbox"/> Not Found	
				<input type="checkbox"/> Reset	
				<input type="checkbox"/> Referenced Out	
Previous Rewitnesses, Restorations, Surveys, etc.: MAPS B-1225, A-5598, A-1209, A-965, & B-404, REWITNESS CARD #395, FIELD BOOK P-1 PAGES 121-124 & 128, REWITNESS BOOK 1, PAGE 320, G.L.O. CONTRACT #500 BLM VOL OR-R0309 P 0958.0, G.L.O. CONTRACT #67 BLM VOL OR-R0053 P 0333.0,					
Found Monument(s) and Accessories(Condition & Source): FOUND OSBF BRASS CAP IN CONCRETE STAMPED "T2S R9W S15 S14 S22 1958 RS 401", FROM WHICH: HAT SECTION 1' SOUTH, 30" (5") HEM. WITH HEALED FACE (S65°W 15.2'); 6" (4") DEAD FIR WITH HEALED FACE (N22°W 4.8'); 46" HEM. STUMP (S62°W70.4'); (38" HEM N12°30'W 73.7') GONE (BTs ARE FROM REWITNESS CARD #395)					
Monument Set(Procedures & Description):				Sketch of Cap	
Other New Accessories Set:					
New Bearing Trees: 18" HEM. SCRIBED "T2S R9W S15 BT" BEARS N17°W 12.75' TO BRASS NAIL AND WASHER "LS 2507" BETWEEN THE B & T; 10" HEM. SCRIBED "T2S R9W S14 BT" BEARS N71°E 10.48' TO BRASS NAIL AND WASHER "LS 2507" BETWEEN THE B & T					
Location & Comments: SOUTH 20' FROM CENTER LINE OF LOGGING ROAD AND 125' EAST OF INTERSECTION OF ROAD THAT RUNS SOUTH				Surveyor's Stamp	
Firm/Agency: BAYSIDE SURVEYING					
Address: 11765 HWY 101 S. TILLAMOOK, OR 97141					
Party Chief: TERRY JONES					
Notes: REWITNESS/2S-9W-S22-NE-COR.xls FILE IN OFFICE				Office Use Only	
Witness(es): KYLER JONES DALLAS ESPLIN					