

OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT  
Tillamook County Surveyor's Office


SECTION: 6	TOWNSHIP: 2S	RANGE: 7W
COUNTY: TILLAMOOK		DATE: JUNE 29, 2016
<b>CORNER DESIGNATION:</b> SW Section corner Section corner common to Sections 6 & 7, T2S, R7W. on East line of Section 1, T2S, R8W.		Also (Please Check One) <input type="checkbox"/> Condition Report Only <input type="checkbox"/> Restoration <input checked="" type="checkbox"/> Rewitness <input type="checkbox"/> Not Found <input type="checkbox"/> Reset <input type="checkbox"/> Referenced Out

**Previous Rewitnesses, Restorations, Surveys, etc.:**  
Rewitness Book 2, Page 121

**Found Monument(s) and Accessories(Condition & Source):**

FOUND OREGON STATE BOARD OF FORESTRY BRASS CAP, STAMPED "T2S R7W R8W S6 S1 S7 CC 1952 2311" IN CONCRETE IN MOUND STONE. FROM WHICH: CARSONITE POST 2' WEST AND HAT SECTION, N75°E 2.0'; FOUND: 45" ROTTEN FIR STUMP, BEARS (N48 1/2° W 18.5'); (15") DOUGLAS FIR, NOW HIGH STUMP 5' TALL WITH HEALDED FACE, BEARS (S34°E 20.27'); 4' (5") ROTTEN FIR STUMP, NO SCRIBING, BEARS (S11 1/2°E) 37.5 (37.0); 6' CEDAR STUB NOW PILE OF RUBBEL (N81° W35.4); 12" (6") FIR STUMP WITH BOTTOM OF HEALDED FACE, BEARS (WEST 17.55'). SEE REWITNESS CARD #341

**Monument Set(Procedures & Description):**



**Other New Accessories Set:**

HAND HELD GPS = LAT. 45.41707 LONG -123.60461  
12' FIR STUMP WITH 80d NAIL AND BRASS WASHER "LS 2507" IN TOP CENTER BEARS WEST 17.80'

**New Bearing Trees:**

NO NEW TREES AVAILABLE

**Location & Comments:**

CORNER IS LOCATED ±625' NORTH OF THE EAST FORK TRASK RIVER ROAD. ±350' NORTH OF THE EAST FORK TRASK RV PARK. ±40' EAST OF TOE HILL. IN A CLEAR-CUT. LAT.= 45.41707 LONG = -123.60461

**Firm/Agency:**

BAYSIDE SURVEYING

**Address:**

11765 HWY 101 SOUTH  
TILLAMOOK, OR 97141

**Party Chief:**

TERRY JONES


**Notes:**

FILE NAME rewitness\T2S-R7W-S6-SW.xls

**Witness(es):**

TLJ/DWE

**Surveyor's Stamp**



renewal date 6-30-17

Office Use Only

