

31	32
6	5

TILLAMOOK COUNTY REWITNESS

3^A

SECTION CORNER 31/32
6/5 T 182N R 6 W., WM.

HISTORICAL: SEE 1982 REWIT CARD

CONDITION

FOUND,

COMMENTS:

REWITNESS

1 SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN CONCRETE FROM
FOUND 1982 B.T.S SEE PREVIOUS CORNER CARD.
" Hat Section

T 2 N R 6 W
S 31/32
S 6/5
T 1 N R 6 W
L S 7 9 3
1987

NEW ACCESSORY:

COMMENTS: 3" (S.H.D.) BRASS CAP
THE CORNER POINT WAS DESTROYED
BY THE STATE HWY. DEPT. DURING HWY SHOULDER WORK.


IN THE PRESENCE OF: DAN MCNUTT
AL DVORAK

DATE: 6-87

PHOTO#: 241111 (L.S. 793) S. S.

* = County corner tag affixed.

TITLE



TILLAMOOK COUNTY REWITNESS

#3⁸

SECTION COR. $\frac{31,32}{615}$ T 142N R 6 W., WM.

HISTORICAL: G.L.O. Pg. 14 IN 6 1874

BOOK	PAGE	MAPS
1	168	F-21-15
69	86	
4	41	


CONDITION GOOD

FOUND 3" BRASS CAP IN CONC. BK 1 Pg 168

GONE	5" MAPLE	S. 30° E.	17 LKS	G.L.O. Pg. 14
GONE	4" MAPLE	S. 64° W.	12 LKS	G.L.O. Pg. 14
GONE	5" MAPLE	N. 65° E.	24 LKS	G.L.O. Pg. 14
GONE	36" FIR	N. 43° W.	18 LKS	G.L.O. Pg. 14
GONE	14" HEMLOCK	S. 37° E.	16°	BK 4 Pg 41
GONE	24" FIR	S. 70° W.	17E	BK 4 Pg 41
GONE	30" FIR	N 74° W.	19E	BK 4 Pg 41
GONE	CONC. O.S.H.D. B.M.	NORTH	8'	BK 1 Pg 168

REWITNESS

I FOUND 3" BRASS CAP IN CONCRETE ± 8" DEEP IN THE NORTH
 SHOULDER OF HWY #6. BOOK 1 Pg 168
 " Hat Section



NEW ACCESSORY:

*23" CEDAR	N. 87° E.	192 ⁶⁷	S 32 B.T CS
*10" CEDAR	S. 57° E.	175 ⁸⁹	S 5 B.T CS
*26" FIR	S. 79° W.	247 ⁵⁵	S 6 B.T CS
*24" FIR	N 72° W.	236 ⁰⁵	S 31 B.T CS

DISTANCES TO NAIL WITH CS BRASS WASHER IN FACE.

COMMENTS: THIS CORNER IS LOCATED ON THE
 NLY. SHOULDER OF OREGON STATE HIGHWAY #6 (AKA WILSON RIVER
 HIGHWAY); IN AN AREA WHICH HAS LARGE CUT BANKS ON BOTH
 SIDES OF THE HWY.

IN THE PRESENCE OF: GALE ARTHUR DAN MCNUTT

DATE: 12-13-82

PHOTO#: 250

* County corner tag affixed.

TILLAMOOK COUNTY REWITNESS TITLE