


TILLAMOOK COUNTY REWITNESS # 80

SEC. COR. $\frac{9}{16} | \frac{10}{15}$ T 2 N R 10 W., WM.

HISTORICAL: G.L.O. 2 N 10 page 32
 Map B-380 by John Carlich

CONDITION	FOUND:	(Map B-380)
Fd. Good	4" x 4" x 4" CEDAR POST	scribed "#287" at corner location.
Fd. in Fair Condition	20" HEM. stamp	no marks visible, bears N 50° W 17.8 ft (G.L.O. bearing tree).
Fd. Badly rotted	30" Hem. stamp	bears S 68° E 32.3 ft (G.L.O. tree).
Fd. very good	84" Cedar stamp	scribed "S 9 BT #287" bears N 10° 30' W 48.3 ft S.D. to face (Map B-380).
Fd. Badly rotted	34" D. Fir stamp	No Marks visible, bears COMMENTS: N 42° 30' E 28.6 ft s.p.,

REWITNESS
 I replaced the cedar post with a
 1 1/2" x 30" IRON PIPE with a BRASS CAP
 set in CONCRETE.



* 60" Hat Section 1.5 East
 NEW ACCESSORY: * 8" Dia. SPRUCE Bears N 37° E 20.80 ft @ 18° slope, to face, scribed "S 10 CS BT".
 * 10" Dia. CEDAR Bears S 24° W 9.66 ft to face Scribed "S 16 CS BT". * 12" Dia. CEDAR Bears S 24° E 18.60 ft to face scribed "S 15 CS BT".

COMMENTS: I replaced John Carlich's 4" x 4" x 4' cedar post with the C.S.B.C.

IN THE PRESENCE OF: TERRY JONES
 GALE ARTHUR

DATE: 7/14/81 PHOTO#: 2807

* = County corner tag affixed. TITLWOCK CONALX BEAIPLEZ2 TITLE