

TILLAMOOK COUNTY REWITNESS #95

INITIAL POINT SEC. 29/32 T 2N R 10 W., WM.
LAKE LYTLE

HISTORICAL: MAP C-7


MAP A-2412		

CONDITION RUSTY FOUND: 2" I.P. WITH PLUG & TACK

COMMENTS:

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT @ POSITION OF FD 2" I.P.
"x "x " Post N.W. feet



* 86 " Hat Section NORTH 15 FEET

NEW ACCESSORY:

* 12" ALDER	N 20° E 24 00'	INT. PT BT CS

COMMENTS: THIS CORNER IS LOCATED IN DENSE BRUSH ± 450' EAST OF LAKE LYTLE. LAYED FD. 2" I.P. ALONGSIDE MONUMENT.

IN THE PRESENCE OF: GALE ARTHUR DAN MCNUTT

DATE: 6-28-79

PHOTO#:

TITLE

* = County corner tag affixed.