

TILLAMOOK COUNTY REWITNESS # 111
 N.W. 10 SEC. 4/3
 COR. 9/10 T 3N R 10 W., WM.
 S. E. 4

HISTORICAL: GLO Pg. 54 3N10 ± 1893

BK	Pg	
2	111	


CONDITION. ^{ROTTEN STUMP} _{SCRIBING ON 2 SIDES} FOUND: ^{ORIGINAL CORNER} 36" HEMLOCK 8' HIGH GLO Pg 54

FD. NOW SNAG	28" HEMLOCK	N40°E 45 LKS	GLO Pg 54
NOT FD.	24" HEMLOCK	S77°E 21 LKS	GLO Pg 54
NOT FD.	14" HEMLOCK	S20°W 46 LKS	GLO Pg 54
NOT FD.	24" HEMLOCK	N5°W 17 LKS	GLO Pg 54
FD. SNAG 5' HIGH ^{ROTTEN} _{SCRIBING READABLE}	6" HEMLOCK	S23°W 16 FT.	BK 2 Pg 111
NOT FD.	10" HEMLOCK	N20°E 26 FT.	BK 2 Pg 111
FD.	3/4" IRON PIPE EAST SIDE OF TREE		BK 2 Pg 111

COMMENTS:

REWITNESS

I SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT
 5 1/2 FEET S 12° W FROM FD. ORIGINAL CORNER STUMP
 86" Hat Section ● EAST 1 1/2 FT.



NEW ACCESSORY:

* 7" HEMLOCK	N 49° W 2 1/2'	RM BT CS
* 7" HEMLOCK	N 38° E 10 3/4'	RM BT CS
* 7" HEMLOCK	S 83° E 7 1/2'	RM BT CS
* 7" HEMLOCK	S 29° W 10 1/2"	RM BT CS

COMMENTS: THIS MONUMENT IS LOCATED ± 25' SOUTH OF THE ~~ROAD~~ SHORT SANDS CROSS OVER ROAD IN A STAND OF HEMLOCK TREES. ORIGINAL CORNER TREE (NOW 36" STUMP 8' HIGH WITH SCRIBING) BEARS N12°E 5 1/2 FT.

IN THE PRESENCE OF: GALE ARTHUR DANMCNUTT

DATE: 3-8-77

PHOTO#:

* = County corner tag affixed.

TILLAMOOK COUNTY REWITNESS TITLE