

28 | 27  
 ---  
 33 | 34

TILLAMOOK COUNTY REWITNESS

#144

Section COR. SEC. 28 | 27  
 33 | 34 T 3 N R 10 W., WM.

HISTORICAL: GLO 3N10 Pg 25

MAPS	BK	Pg
F-40-160	10	98
F-40-182	53	350
A-176	4	98
A-305	5	90

CT9 9# 27-29

CONDITION

FOUND: 1" AXLE

Field Condition 1970			
16" Pine N24°W 34.82	14" Pine N18°W 34.8	BK 4 Pg 98	*
16" Pine S38°W 76.98	10" Pine S45°W 77.0	BK 4 Pg 98	*
56" Spruce S70°E 70.12	48" Spruce S65°E 70.1	BK 4 Pg 98	* This tree destroyed
ABOVE DIST. S' TO FACE OF TREE			1M 5cm. approx. 1994

COMMENTS: \* 16" PINE N24°W 34.82 Now 23" FACE HEALED 8-1-94  
 \* 16" PINE S38°W 76.98 Now 19" FACE HEALED 8-1-94

REWITNESS


SET IN CONCRETE & TILE 1972

1 SET 2" Iron Pipe with 3" Brass Cap over 1" AXLE

T3NR10W  
 28 | 27  
 ---  
 33 | 34  
 RS287  
 1970

\* 36" Hat Section \* 1.5 ft SW

NEW ACCESSORY:

COMMENTS: Corner is located 7 feet south of ditch line P.I.

IN THE PRESENCE OF:

Al Duncan G. Arthur 1972  
 George Urvey R. Knipple 1972  
 Gale Arthur

DATE: 1-20-70

PHOTO#:

\* = County corner-tag affixed.

TITLE  
 GLO