

TILLAMOOK COUNTY REWITNESS

#260

~~SEC. S~~ SEC. S 34 | 35 1 S 9
 SECTION COR. 3 | 2 T 2 S R 9 W., WM.


Corner was a 1" Iron Pipe.
 HISTORICAL: Corner set by proportion in 1952 by County Surveyor - W.E. Anderson.
 BT's were as follows: Book 5 Page 116
 16" fir N42°W 45 1/2 feet
 12" Spruce N62°E 81 1/2 feet MAP A-2062
 Bk 1 Page 97 Bk 4 Page 91 & 12-15 MAP B-301
 MAP A-2088 MAP A-2105 MAP A-77 MAP B-516

CONDITION		FOUND:	
Good		1" Iron Pipe	
Good	Now 20"	16" fir	N42W 45 1/2 feet
Good	Now 18"	12" Spruce	N62E 81 1/2 feet

COMMENTS: Field check Dec 1971 BT.S & cor. still in position
 Gale Arthur
 Roger Knipple

REWITNESS

Corner has been cemented
 I SET 2" Iron Pipe with 3" Brass Cap over the 1" Iron Pipe
 "x" "x" "Post N. 1/2" feet



* 96 "	Hat Section	North 20 feet
NEW ACCESSORY: I USED W.E. ANDERSON BT'S.		
* 20" fir	N42°W	45 1/2 ft
* 18" Spruce	N62°E	81 1/2 ft

COMMENTS: Set 2" Iron Pipe with Brass Cap over the 1" Iron Pipe set by W.E. Anderson in 1952.

GLO BT'S are all gone.

IN THE PRESENCE OF: Gale Arthur
 Gary McQuire
 Paul CHAPIN

DATE: 7-17-68 PHOTO#:

* - County corner tag affixed. TITLE Gwu