

TILLAMOOK COUNTY REWITNESS #312

SEC. 22  
 1/4 COR. 27 T 1 S R 10 W., WM.

HISTORICAL:

|         |      |      |        |
|---------|------|------|--------|
| GLO     | Bk 1 | S 10 | pg 32  |
| Collard | Bk 2 |      | pg 477 |
|         |      |      |        |
|         |      |      |        |

CONDITION

FOUND:

|                         |   |
|-------------------------|---|
| Fd (GLO) Badly rotted   | Mem. Stamp bears N 4 1/2° W 4° ft to center                               |
| Fd (GLO) wind fall      | 32" Hem. Dead end Down, badly rotted, bears S 13° W 27 1/2 ft approx.     |
| Fd Good (Collard)       | 32" Hem. Stamp, No mark visible, bears S 3 E 53 1/2 ft to said spike.     |
| Fd Badly rusted, 1 1/2" | IRON PIPE (Collard) at the corner position.                               |
| Fd Good (Collard)       | 24" Hem. with healed over face bears S 61° W 15 1/2 ft to center of tree. |

COMMENTS:

20" Hem. unrecorded BT bears N 48° W 19 2/3 ft to face

REWITNESS


I SET A 1 1/2" x 30" IRON PIPE with a BRASS CAP SET IN CONCRETE.

60" Hat Section | 5 West 4"x4" white post 1° W

NEW ACCESSORY:

Collard BT with healed face, now 2" Hemlock bears S 61° W 14 1/2 ft to my new face scribed "CS BT".  
 Unrecorded BT with healed face, approx. 10 yrs old, now a 20" Hemlock bears N 48° W 19 2/3 ft to new face I scribed "CS BT".

COMMENTS: I replaced the 1 1/2" IRON PIPE with a C.S.B.C.



The corner lies approx. 400 ft West of the Crown road ~~road~~, just off of a old catd.

IN THE PRESENCE OF: TERRY JONES  
 GALE ARTHUR

DATE: 6/12/81

PHOTO#: 210

\* = County corner tag affixed.

TITLE