

TILLAMOOK COUNTY REWITNESS #333

N.W. 4 SEC. 32/33  
 COR. 5/4 T 1&2S R 10 W., WM.  
 S. E. 32

HISTORICAL: GLO Pg. 8 2510 ± 1857

BOOK	PAGE	MAPS
S 3	152	A-231 A-1973
4	82	B-659
S 3	196	B-658
1	92	B-583


CONDITION GOOD FOUND: 1" IRON PIPE

FD. ROTTEN SNAG	48" SPRUCE	N 60° E	100 LKS	GLO Pg. 8
FD. ROTTEN SNAG	88" SPRUCE	N 55° W	45 LKS	GLO Pg. 8
NOT FD.	56" SPRUCE	S 65° W	43 LKS	GLO Pg. 8
FD. UPROOT	48" SPRUCE	S 30° E	14 LKS	GLO Pg. 8
FD. GOOD NOW 30"	6" SPRUCE	N 66° E	93 FT.	BK 4 Pg. 82
FD. GOOD NOW 30" SCRIBING VISIBLE	6" SPRUCE	SOUTH	60 FT.	BK 4 Pg. 82
FD. GOOD NOW 24"	6" SPRUCE	S 52° W	73 FT.	BK 4 Pg. 82
FD. GOOD. NOW 30"	8" HEMLOCK	N 5° W	200 FT	BK 4 Pg. 82

CROWN TAGS ON GOOD BT's

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT  
 IN POSITION OF FD 1" I.P.  
 FD. 4" x 4" x 60" Post NORTH 13 feet  
 " Hat Section S. E.



NEW ACCESSORY:


COMMENTS: THIS CORNER IS LOCATED ± 400 FT. WEST OF THE END OF A ROCK ROAD MUDDY CAT RD CONTINUES ON AND WINDS UP ± 100 FT. EAST OF THE CORNER CORNER IS ± 100' WEST, MUD CAT ROAD CONTINUES ON NORTHERLY

IN THE PRESENCE OF: GALE ARTHUR DAN McNUTT

DATE: 11-15-77

PHOTO#: 2507

TILLAMOOK COUNTY REWITNESS TITLE

\* = County corner tag affixed.