


#349

TILLAMOOK COUNTY REWITNESS



C.N. ~~1/4~~ SEC. 3 T 2S R 9 W., WM.
 COR. ~~1/16~~ ~~1/16~~


HISTORICAL:
 MAP B-301 WE Anderson 1952 Subdivision
 F-9-2
 Book 5 Page 102 (witness corner)

CONDITION	FOUND:
Good	WC — 1 1/2" Cap on 1" I.P. (ground rod)
Good	Fd witness cor in EAST-WEST, SOUTH fence intersect
Good	Fd W. cor B.T. 20" spr
Good	Fd Power Pole No. 58 (w.c. Bearing Object) Δ hub tack

COMMENTS:

REWITNESS
 CORNER CEMENTED 1971

1 SET 2" Iron Pipe with Brass Cap located South edge oil.
 "x "x " Post ~~N.W.~~ feet



*96 " Hat Section S. R. SOUTH 82
 NOW BENT 929 12-6-88
 NEW ACCESSORY:
 *20" Spruce Bears S16°W 72 LB
 Power Pole D20-58 S83°E 13022 Δ Finish nail
 (Fd hub tack 4" above set finish nail)

COMMENTS: Above 20" Spruce is same tree used for
 Witness Corner Bearing tree. SET HAT SECTION IN A S & E-W FENCE
 CORNER.

IN THE PRESENCE OF: Al Duncan RS 793
 Gale Arthur
 George Urrey

DATE: 11-3-70

PHOTO#: 712

* = County corner tag affixed.

TITLE