

T1S R9W WM

TILLAMOOK COUNTY REWITNESS

354

34
3

1 N. 3
4 S. 34
COR.

SEC.

34
3

IT 1+25 R 9 W., WM.

HISTORICAL: GLO Pg 50 SET POST ± 1857

BOOK PAGE	MAPS	F. 40-65
53 52-54	B-301	F-17-18
43 77	A-643	
5 116	A-675	
	A-650	

T2S R9W WM

SEE SURVEY NOTES FOR
RACHEL WESTON T1S R9W

CONDITION

FOUND: 1" IRON PIPE ± 6" ABOVE GROUND

COND	FOUND	BEARING	DISTANCE	REFERENCE
GONE	8" VINE MAPLE	S. 38° E.	19 LKS	GLO Pg 50
GONE	72" SPRUCE	N. 22° E.	54 LKS	" "
GOOD	24" ALDER	N. 05° W	180 ± 5"	BOOK 5 Pg 116
GOOD	24" ALDER	N. 42° E.	176 ± 5"	

COMMENTS:

REWITNESS

COMMENTS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE FILLED CONCRETE
OVER FOUND 1" IRON PIPE
84" Hat Section EAST 15

1/4 S 34 159
4 S 3 259
RS 287
1974

NEW ACCESSORY:

16" SPRUCE N 25 E	164 38
DO NOT CUT TAGS AND YELLOW CORNER TAGS ON ALL BTS	

COMMENTS: THIS CORNER IS LOCATED IN EAST-WEST
AND NORTH FENCE LINE. AND ± 200 FEET
SOUTH OF OLD RIVER BED.

IN THE PRESENCE OF: GALE ARTHUR - DAN MC NUTT

DATE: 10-1-74 PHOTO#:

* - County corner tag affixed.

TITLE