


R 10 W COR. R 9 W

TILLAMOOK COUNTY REWITNESS

#367



1/4 W. 7 D. 10 SEC.  
COR. E. 12

1217 T 25 R 910 W., WM.

HISTORICAL: G.L.O. Pg. 2. 2510 ± 1857

BOOK	PAGE	MAPS
5	349	F-22-14
10	75	F-19-25
		B-700


CONDITION GOOD FOUND: 2" I. P. WITH 3" CZ BRASS CAP

FD. ROTTEN REMAINS	32" SPRUCE	N. 10° E.	43 LKS	G.L.O. Pg 2
NOT FD.	8" BEAR BERRY	S. 80° W.	26 LKS	G.L.O. Pg 2.
? FD. STUMP	60" FIR	S. 0° 45' W.	390 LKS.	BK. 10 Pg 79
FD. GOOD	30" FIR	S. 27 1/2° E.	399'	MAP B-700
FD. GOOD	6" CHERRY	S. 3° W.	13 1/2'	MAP B-700
FD. GOOD	6" ALDER	N. 85° W.	28 1/2'	MAP B-700

COMMENTS:

REWITNESS

1 SET 10" TILE & CEMENT AROUND FD. CROWN ZELLERBACH 2" IRON PIPE WITH 3" BRASS CAP  
86" Hat Section N.W. 1 1/2'



NEW ACCESSORY:


COMMENTS: THIS CORNER IS LOCATED ± 40' EAST OF A CAT ROAD WHICH IS ON A RIDGE IN A PATCH OF VINE MAPLE. ALSO FD. 1" I.P. SET IN 1915 LAYING ALONGSIDE CZ MONUMENT

IN THE PRESENCE OF: GALE ARTHUR DAN MCNUIT

DATE: 3-79

PHOTO#: 31019

TITLE

\* = County corner tag affixed.