

TILLAMOOK COUNTY REWITNESS

#375

SEC. 8 T 2S R 9 W., WM.

S. E.

HISTORICAL: ^{Page 15} GLO-1857 - drove charred stake

MAP B-30	1931	WEANDERSON	
Book 1 Page 96	1951	WEA = BKA Pg 89	WEA 1951
Book 3 Page 228	#229	JLC	1967

CONDITION

FOUND: 1/2" Iron Pipe ± 150" North of Cultivated field


Double Willow Fallen/Rotted	14" Willow	S53°W	88 ³ / ± 88 ³	Bk 1 Pg 96	1951
Dead Spruce 6" / Scribing Visible	4" Spruce	N32°E	7° / 6 ⁵⁴ disturbed STUMP	BK 1 Pg 96	1951
Dead stub with Visible Scribing	3" Barberry	N07°W	8° / 7 ⁹⁸ To FACE	BK 1 Pg 96	1951
Fallen / Rotting Stub (Visible face)	3" Barberry	S62°E	9° / ± 9° Field	BK 1 Pg 96	
School Marm Spruce 24"	*14" Spruce	N01°E	112 ¹⁸ / 111 ⁹³ FIELD TO FACE	BK 3 Pg 228#9	
Fallen 25" Spruce (TAG STILL ON TREE)	16" Spruce	S53°E	326 ⁴⁵ / ± 326 Field	BK 3 Pg 228#9	

THE ABOVE "B.T.S" REFERED TO AS "BARBERRY" WERE FOUND COMMENTS: TO BE WILD CHERRY TREES.

REWITNESS

Set 2" Iron Pipe over Fd 1/2" Iron Pipe

1 SET 2" Iron Pipe with 3" Brass Cap in 8" Tile and Concrete ± 8" High
 4" x 7" x ± 80" Post N.W. S 20W 10
 ± 80" Hat Section S. E. N 20 E 06



NEW ACCESSORY:

*12" Spruce N59°W 22935

COMMENTS: Found ± 80" Hat Section set by JLC. ^{RS 287}

The Cedar Post described in book 3 is an old fence post with a 2"x6" x 36" Board painted yellow nailed to the side of the fence post. Corner is ± 300 from dense timber growth. Scotch broom - Swamp grass at corner

IN THE PRESENCE OF: Gale Arthur
 Geo Urrey
 Roger Knipple

DATE: 4/72

PHOTO#:

* = County corner tag affixed.