

#423

FOREST SERVICE (PFD 720-117)

CORNER RECORD (SEARCH) (Ref. FSM 715T.4)

Tract or Survey No. 7-11 Cor. No. 3

File No. 2 S R 9 W R.D. HEBO County TILLAMOOK State ORE

Merid. WILL N.F. SIUSLAW

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND LINCOLN WILKES, G.L.O. 1896
 CEDAR POST AND MARKED:
 16" Hem., N. 86° W., 33 LKS.
 18" Hem., S. 27° W., 32 LKS.

REFER TO CS #
 MAP B-499/ALSO
 SEE BOOK 2 Page 257

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND $\frac{3}{4}$ GALV. PIPE 12" ABOVE GROUND IN CENTER OF OLD LOG ROAD, N. 86° W.

FOUND 26" SAWED OFF ROTTED HEM. STUMP, 21 FT. WITH OLD SCRIBE MARKS "4SBT" SHOWING.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FOUND 30" SAWED OFF ROTTED HEM. STUMP, WITH CENTER ROTTED OUT.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____ Signature _____

LANE COORDINATE POSITION DATA

State _____ Zone _____

Estab. By _____ Signature _____ Title _____ Division _____ Headquarters _____ Date _____

Edward Whitmore Tilla. Co. deputy surveyor 11-20-69 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

APRUE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW B.T.N. WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

MARK 8" HEM., N. 74° W., 24 FT. TO NAIL HEAD AT SCRIBED "B" ON

SC MARKED $\frac{1}{2}$ S 33 BT CS.

OTHER WITNESS IS CONVENIENT.

TIGUARD (ALUM) POST ALONGSIDE PIPE WITH PENALTY TO DESTROY 5' IN

REACHED. Edward Whitmore deputy Tilla. Co. surveyor 11-20-69

Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Filed Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS

Edward Whitmore is a Deputy County Surveyor empowered to be witness positive old evidence of G.L.O. corners.

4/18/84 J.L. Carter Co. Surveyor

Tract or Surv. No. SEC 33 Cor. 5