


CORNER RECORD (SEARCH) (Ref. FSM 7151.4)

No. 2 S R 9 W Tract or Survey No. 2-15
 Merid. Will. R.D. Hebo County TILLAMOOK # 424
 N.F. STUSLAW State ORE.

CORNER DIAGRAM


DESCRIBE CORNER MONUMENT FOUND
 FOUND WILKES, GLO 1896, SET POST IN MOUND OF STONE, MARKED:
10" FIR, N. 48° W., 6 LKS.
8" FIR, S. 80° 20' E., 24 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 1 1/4" GALV. PIPE 4" ABOVE GROUND WITH A 4' X 4' X 30 HARD FIR LIMB POST SCRIBED 1/4 S 34 ON NORTH SIDE.
 FOUND 20" FIR, N. 51° W., 4 FT. TO WEALED WITNESS FACE.
 FOUND 16" FIR STUB, S. 83° E., 14 1/2 FT. TO FACE WITH

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER.
 VISIBLE SCRIBE MARKS "S"
 FOUND 25" HEM., N. 55° E., 17 1/2 FT. TO FACE WITH VISIBLE SCRIBE MARKS 1/4 S 34 BT 287.
I SET ALUMINUM GUARD POST, ALONG SIDE PIPE, WITH "PENALTY TO DESTROY" AND LOCATION SIGNS ATTACHED.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____ Agency _____

Signature Leonard Whitmore Title Forestry Tech Division Timber Headquarters Hebo Date 11-28-69 7100-52 (3/68)

REWITNESS

I SET _____ "x" _____ "x" _____ " Post N.W. _____ feet
 _____ " Hat Section S.E.

NEW ACCESSORY:

COMMENTS: back side of front is blank

IN THE PRESENCE OF: _____

DATE: _____ **PHOTO:** REC _____
 _____ **TITLE:** _____

County corner tag affixed.