

TILLAMOOK COUNTY REWITNESS # 425

|   |         |
|---|---------|
| 5 | 34      |
|   | CS 1/16 |

SEC. 34 T 25 R 9 W., WM.

HISTORICAL: SEE FRONT


|  |  |  |
|--|--|--|
|  |  |  |
|  |  |  |
|  |  |  |
|  |  |  |

| CONDITION | FOUND: |
|-----------|--------|
|           |        |
|           |        |
|           |        |
|           |        |
|           |        |

COMMENTS:

REPORT ON CORNERS OF THE CADASTRAL SURVEY GRID

T 25 R 9 W. Tillamook Mer. Oregon State.



- SYMBOLS
- CORNER SET
  - Official corner found.
  - Corner found, authenticity doubtful.
  - Corner searched for and not found.

DESCRIPTION OF CORNER MONUMENT

3/4" Iron Reinforcing Rod, Set in Rock with a mound of stone.

DESCRIPTION OF BEARING TREES, MOUND OF STONE, ETC.

one location tag, corner bears N 50° E FOR 39.4' slope distance from a 13" DBH cedar tree.

DESCRIPTION OF LOCATION TO ENABLE RECOVERY BY OTHERS.

Located along a blazed line in a draw on a solid rock side slope.

3-26-73

Form 9180-23 (October 1964) (formerly 4-1226)

Reported by D. STARK Forester U.S. DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT