

TILLAMOOK COUNTY REWITNESS # 467

1/4 SEC. COR. 25/30 + 25 R11-10 W., WM. E. 1/4

HISTORICAL: GLO T25R11W Pg. 2

A	B	Book	Page
A-661	B-78	4	50
A-1832	B-109	3	48
F-7-6	B-371	34	113
F-17-24			
F-14-24			

CONDITION

FOUND:


Gone	24" Spruce S79°E 73 ^{1/2} = 48 ^{1/2} ft	GLO Pg 2
Gone	6" Spruce S71 ^{1/2} °W 19 ^{1/2} = 12 ^{5/8} ft	GLO Pg 2
* Fd 40" double Spruce	8" Spruce S23°E 28 ⁷	BK 4 Pg 50
* Fd 30" double Spruce	10" Spruce N25°E 13 ⁰	4 50
* Fd 27" Spruce (face healed)	16" Spruce N79°E 18 ^{7/9}	3 48
Gone	4x4x48" post South 1 ⁰	3 48
Fd 40" spruce stump	40" Spruce S63°W 118 ⁵	MAP A-661

COMMENTS: Buried in sand dune

REWITNESS

SEE CARD #2 FOR REPLACEMENT OF BROKEN CAP. #468

1 SET 2" Iron Pipe with 3" Brass Cap in Concrete and tile



* 96 " Hat Section	5	15 feet
NEW ACCESSORY:		GONE 10-29-03

COMMENTS: Corner is located at the northerly end of Cape Lookout Camp sites. There is a turn-a-round at the northerly end and the corner is ± 100 Northerly of the turn-a-round.

IN THE PRESENCE OF: Geo. W. Urrey
Gale Arthur
Roger Knippel

DATE: 5-18-72

PHOTO # 32C

= County corner tag affixed.

TITLE