


1. T 3 S R 7 W No. R-7 Cor. $\frac{1}{4}$ Mer. Will. State ORE. N.F. Siuslaw Dist. Hebo

#476

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where recorded ~~1976~~

4. Description of Corner: 1894
Stone 12 x 10 x 10, mKd. $\frac{1}{4}$ on N. face.

5. Investigation Notes:

Stone found mKd. $\frac{1}{4}$.
fir 30 in., S. 84° W., 41 LKS., mKd. $\frac{1}{4}$

7. PHOTO IDENTIFICATION

Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data

State: _____ Zone _____
X _____
Y _____
Est. By _____
Field Book No. _____
Where Filed: _____

9. EVALUATION

Authentic _____
Needs Verit. _____ Manum.
Re-Est. _____ Survey _____
Land Status OC. - DRIV. - P.D.

6. Signed L. WHITMORE Title FORESTER AID Date 4-20-60

10. MONUMENT

PERPETUATION RECORD

11. ACCESSORIES

Fir 6 in., S. 84° W., 41 LKS., mKd. $\frac{1}{4}$ SBT
FIR 6 in., N. 76° E., 47 LKS., mKd. $\frac{1}{4}$ SBT

Field Book _____ Page _____

12. Set By _____ Title _____
License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
(Date) _____ (City) _____ (County) _____ (State) _____

14. REMARKS:

Location poster on bearing tree.
Follow blazed line from s.w. cor. of sec. 20.
MERVIN WHITMORE WAS A DEPUTY COUNTY SURVEYOR
EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE
OF ORIGINAL MONUMENTS.
BY M.W. 6-26-54
M. W. Carlin County Surveyor
2/25/71