

Index File No. R-5 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. #477 Cor. No. ---

T 38 R. 8W R.D. HEBO County TILLA

Merid. WILL N.F. SIUSLAW State ---

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLO 1884 SET POST & MARKED

56" FIR SNAG, S. 52° E, 91 LKS.

30" FIR SNAG, N. 37° E, 151 LKS.

4" MAPLE, S. 18° W, 13 LKS

4" MAPLE, N. 32° W, 18 LKS

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 4" X 4" X 24" OLD MASS COVERED SQUARED POST. No. M. FT.

ARE SHOWING.

FOUND A MOUND OF ROTTEN FIR STUMP, S. 52° E, 60 FT.

FOUND 36" SNAG, N. 39° E, 100 FT. THE SHELL HAS ROTTED AWAY.

FOUND A BLM LOCATION SIGN MARKED "T.H.M. 5-15-57"

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

A 28" FIR, N. 85° E, 9 FT.

L. Whitmore 5-4-73

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____ Signature _____

PLANE COORDINATE POSITION DATA

State _____

Estab. By _____ Agency _____

Signature Leonard Whitmore Title Forestry Tech Div. Timber Headquarters Hebo Date 5-4-73 7100-52 (3)

REWITNESS

I SET _____

"x" "x" " Post N.W. feet

" Hat Section S. E.

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF: _____

DATE: _____

PHOTO# _____

TITLE _____

* - County corner tag affixed.